

NOTIFICATION OF AVIATION OCCURRENCE				
E-ma <u>BG-SIA@ntib.bg</u> ; Tel: +359889601266 9, Dyakon Ignattii Street, 1000 Sofia, Bulgaria				
a) for accidents the abbreviation ACCID, for serious incidents INCID;	ACCIDENT			
b) manufacturer	Cessna Aircraft Company			
model	Cessna 182P			
nationality	USA			
registration marks	LZ-SDB			
serial number	182-63886			
of the aircraft;				
c) name of owner,	"SKYADVENTURES BULGARIA " LTD			
operator	"SKYADVENTURES BULGARIA " LTD			
and hirer				
if any, of the aircraft				
d) qualification of the pilot-in- command	CPL(A); EMB170/IR/PBN; SEP (land) Bulgarian			
nationality of crew				
nationality of passengers	Bulgarian			
e) date and time UTC	July 06, 2024, 5:43			
local time or UTC	July 06, 2024, 8:43			
of the accident or serious incident;				
f) last point of departure and point of intended landing of the aircraft;	Departure: LBSP– Sapareva Banya Intended landing: LBSP – Sapareva Banya			
g) position of the aircraft with reference to some easily defined geographical point, and latitude and longitude	LAT: 42°18'52.804"N LON: 23°15'38.904"E			
h) number of crew and passengers;	Persons on Board			
aboard, killed and seriously injured; others, killed and seriously injured;		Crew	Passenger	Others
	On board	1	4	
	Fatal			
	Serious			
	Minor			



AIR, MARITIME AND RAILWAY ACCIDENT INVESTIGATION NATIONAL BOARD

i) description of the accident or serious incident, and the extent of damage to the aircraft so far as it is known;	On 06.07.2024, a Cessna 182P aircraft with registration LZ-SDB performs a flight from LBSB airport for parachute operations skydiving. At about 05:43 h UTC, during the take-off roll, the pilot felt a diversion to the right and loss of speed. At a speed of about 55 knots the pilot decided to abort the takeoff and attempt to stop the aircraft by pushing the brakes. However, the aircraft failed to stop within the runway. Subsequently it impacted the right main landing gear on a concrete pedestal located approximately 50 m from the threshold of Runway 25, nosed over and stopped in an oat field. As a result of the impact the aircraft received significant damages. The pilot and the four parachutists left the cockpit uninjured.			
j) an indication to what extent the investigation will be conducted or is proposed to be delegated by the State	Bulgarian AAIB will conduct a safety investigation.			
of Occurrence;				
k) physical characteristics of the				
accident or serious incident area, as well as an indication of access				
difficulties or special requirements				
to reach the site;				
i) identification of the originating authority and means to contact the	9, Dyakon Ignatii Street 1000 Sofia Bulgaria			
investigator-in-charge and the	Air, Maritime and Railway Accident Investigation National			
accident investigation authority of	Board			
the State of Occurrence at any time;	BG-SIA@ntib.bg			
m) presence and description of	None			
dangerous goods on board the aircraft.				
Operation Type	Non-Commercial Air Transport			
(If information is available)				
Level of damage to aircraft	Significant			
(If information is available)				
The State of Occurrence shall forward a notification of an accident or serious incident with a minimum of delay and by the most switchle and swickest means available to: a) the State of Registry b) the State of				

The State of Occurrence shall forward a notification of an accident or serious incident with a minimum of delay and by the most suitable and quickest means available to: a) the State of Registry; b) the State of the Operator; c) the State of Design; d) the State of Manufacture; and e) the International Civil Aviation Organization, when the aircraft involved is of a maximum mass of over 2 250 kg.