

NOTIFICATION OF AVIATION OCCURRENCE				
E-mail: BG-SIA@ntib.bg; Fax: +35929409828; Tel: +35929409864 9, Dyakon Ignattii Street, 1000 Sofia, Bulgaria, https://www.ntib.bg/				
a) for accidents the abbreviation ACCID, for serious incidents INCID;	ACCIDENT /AC	CCID/		
b) manufacturer	"PZL-MIELEC"			
model	M-18 A DROMADER			
nationality	R Poland			
registration marks	LZ-DRB			
serial number	IZ015-13			
of the aircraft;				
c) name of owner,	KMK Ltd			
operator	KMK Ltd			
and hirer				
if any, of the aircraft				
d) qualification of the pilot-in-	CPL(A) Bulgarian			
command nationality of crew				
nationality of passengers	N/A			
e) date and time UTC				
local time or UTC	June 28 2025, 03:30 June 28 2025, 06:30			
of the accident or serious incident;	June 28 2025, 06:30			
,	D 4 42012	10.4.5431.2.402	0110.205	
f) last point of departure and point of intended landing of the aircraft;	Departure: 42°13'04.5"N 24°38'18.3"E Intended landing: 42°13'04.5"N 24°38'18.3"E			
g) position of the aircraft with reference to some easily defined geographical point, and latitude and longitude	LAT: 42°13'30.1	57"N; LON:	25°47'21.074"E	
h) number of crew and passengers;	Persons on Board			
aboard, killed and seriously injured; others, killed and seriously injured;		Crew	Passenger	Others
omers, kined and seriously injuica,	On board	1		
	Fatal			
	Serious			
	Minor			



AIR, MARITIME AND RAILWAY ACCIDENT INVESTIGATION NATIONAL BOARD

i) description of the accident or serious incident, and the extent of damage to the aircraft so far as it is known;	On June 28, 2025, the PZL M18 A "Dromader" aircraft, registration marks LZ-DRB, performed an agricultural flight (fertilization of rice crops with urea) from the Benkovski airfield. Two minutes after take-off, at about 03:32 UTC, at an altitude of 5060 m, the engine shut down by itself, so the pilot performed a forced landing on a site selected from the air, a sunflower field. The aircraft touched down in a concrete groove turned and stopped in the field. The pilot evacuated from the cabin without injury. As a result of the impact, the aircraft was destroyed.		
j) an indication to what extent the investigation will be conducted or is proposed to be delegated by the State of Occurrence;	Bulgarian AAIB will conduct a safety investigation.		
k) physical characteristics of the accident or serious incident area, as well as an indication of access difficulties or special requirements to reach the site;	Sunflower crop		
i) identification of the originating authority and means to contact the investigator-in-charge and the accident investigation authority of the State of Occurrence at any time;	9, Dyakon Ignattii Street 1000 Sofia Bulgaria Air, Maritime and Railway Accident Investigation National Boar BG-SIA@ntib.bg;		
m) presence and description of dangerous goods on board the aircraft.	None		
Operation Type (If information is available)	Specialized Operations (Aerial Work)- Agricultural		
Level of damage to aircraft (If information is available)	Destroyed		
The State of Occurrence shall forward a notification of an accident or serious incident with a minimum of delay and by the most suitable and quickest means available to: a) the State of Registry; b) the State of the Operator; c) the State of Design; d) the State of Manufacture; and e) the International Civil Aviation Organization, when the aircraft involved is of a maximum mass of over 2 250 kg.			

Page 2 of 2