

| NOTIFICATION OF AVIATION OCCURRENCE | | | | |
|--|---|--------------|-----------|--------|
| E-maBG-SIA@ntib.bg; Tel: +35988960 9, Dyakon Ignattii Street, 1000 Sofia, B | | | | |
| a) for accidents the abbreviation ACCID, for serious incidents INCID; | ACCIDENT | | | |
| b) manufacturer | Cirrus Aircra | ft | | |
| model | Cirrus SR22 | | | |
| nationality | USA | | | |
| registration marks | N67DP | | | |
| serial number | 2933 | | | |
| of the aircraft; | | | | |
| c) name of owner, | Private owner | r | | |
| operator | | | | |
| and hirer | | | | |
| if any, of the aircraft | | | | |
| d) qualification of the pilot-in- command | SEP (land) | | | |
| nationality of crew | Bulgarian | | | |
| nationality of passengers | Bulgarian | | | |
| e) date and time UTC | June 28, 2025, 05:50 | | | |
| local time or UTC | June 28, 2025, 08:50 | | | |
| of the accident or serious incident; | | | | |
| f) last point of departure and point of intended landing of the aircraft; | Departure: Petrich Airfield Intended landing: LBRS | | | |
| g) position of the aircraft with reference to some easily defined geographical point, and latitude and longitude | 41°43'19.3"N | 23°26'42.6"E | | |
| h) number of crew and passengers; | Persons on Board | | | |
| aboard, killed and seriously injured; others, killed and seriously injured; | | Crew | Passenger | Others |
| | On board | 1 | 2 | |
| | Fatal | | | |
| | Serious | | | |
| | Minor | | 1 | |



AIR, MARITIME AND RAILWAY ACCIDENT INVESTIGATION NATIONAL BOARD

| i) description of the accident or serious incident, and the extent of damage to the aircraft so far as it is known. | On 28.06.2025, a small aircraft Cirrus SR22, registration N67DP, performed a pleasure flight from Petrich Airfield. to LBRS /Ruse/. During the climb to 10 000 ft above Pirin Mountain, the pilot identified engine problems and made a forced landing in a rocky area below Vihren Peak, near Spano Pole. When skidding on the ground it is hit in a large stone and stopped. As a result of the impact, the aircraft sustained significant damage. The pilot and two passengers left the cockpit and moved to nearby mountain shelter on their own, two of them were minorly injured and the other with serious injuries and was transported by helicopter to a hospital. | | |
|--|--|--|--|
| j) an indication to what extent the investigation will be conducted or is proposed to be delegated by the State of Occurrence; | Bulgarian AAIB will conduct a safety investigation. | | |
| k) physical characteristics of the accident or serious incident area, as well as an indication of access difficulties or special requirements to reach the site; | | | |
| i) identification of the originating authority and means to contact the investigator-in-charge and the accident investigation authority of the State of Occurrence at any time; | 9, Dyakon Ignatii Street 1000 Sofia Bulgaria Air, Maritime and Railway Accident Investigation National Board BG-SIA@ntib.bg | | |
| m) presence and description of dangerous goods on board the aircraft. | None | | |
| Operation Type (If information is available) | Non-Commercial Operations-Pleasure-Local | | |
| Level of damage to aircraft (If information is available) | Substantial | | |
| The State of Occurrence shall forward a notification of an accident or serious incident with a minimum of delay and by the most suitable and quickest means available to: a) the State of Registry; b) the State of the Operator; c) the State of Design; d) the State of Manufacture; and e) the International Civil Aviation Organization, when the aircraft involved is of a maximum mass of over 2 250 kg. | | | |